

# Review on Analysis of Irregular Structures under Earthquake Load (Vertical and Horizontal Irregularity)

JAIN PRITAM ANIL, VAIBHAV. V. SHELAR

ME Student, Department of Civil Engineering, (ME Structure), KJEI's Trinity College of Engineering & Research, Pune, India

Professor, Department of Civil Engineering, (ME Structure), KJEI's Trinity College of Engineering & Research, Pune, India

**ABSTRACT:** Previous earthquakes in India have discovered that most of the buildings aren't designed to be earthquake resistant. In general, buildings are designed taking into account just the gravity loads. Furthermore, the present look seismic codes are not completely practiced while developing a building. a thus a thus higher degree of damage might be expected during an earthquake in case the seismic resistance of the structure is insufficient. The existing work describes the various reinforced concrete (RC) frames having various irregularities but with same dimensions which are analyzed to study the behaviour of theirs when put through seismic lateral loads. All of the frames were analyzed with the same strategy as mentioned in Is 1893-Part-1:2002. By the end result, it's been interpreted the base frame (regular) evolves least story drifts while the structure with floating columns shows maximum storey drifts on the soft story levels. Hence, this's very vulnerable to damages under this particular type of loading. The structures with irregularities also proved unsatisfactory consequences to some degree. The frame with heavy loads produces maximum storey shears, which ought to be accounted for in design of columns suitably. The evaluation proves that irregularities are unsafe for the buildings and it's crucial that you have regular and simpler shapes of frames in addition to uniform load distribution within the building. Thus, as far as possible irregularities in a construction must be stayed away from. Nevertheless, if irregularities need to be introduced for every reason, they should be designed properly following the circumstances of Is actually 13920:1993. The complex shaped structures are days getting common, but they have a threat of sustaining damages during earthquakes. Thus, such buildings must be designed effectively taking proper care of the dynamic behaviour of theirs.

**KEYWORDS:** Dynamic response, structural irregularity, mass irregularity, stiffness irregularity

## I.INTRODUCTION

### 1.1 GENERAL

Vertical irregularities in structures are extremely typical function in Area that is urban. In many of situations, buildings start to be vertically irregular within the planning phase itself as a result of several architectural and functional purposes. This kind of buildings demonstrated more vulnerability within the past earthquakes. The topics regarding of vertical irregularities have been in focus of research for many years. Numerous studies have been performed in this specific area in deterministic domain. Hence the focus of existing study is assessing the relative performances of typical vertically irregular structures in a Probabilistic domain.

This kind of irregularities arises because of unexpected reduction of strength or stiffness in a specific storey. For extremely high seismic zone area, irregularity in building is probably a great problem to an excellent structural engineer. A lot of vertical irregular buildings occur in modern-day urban infrastructures. Among them Open ground storey as well as stepped kinds of structures are extremely typical in Urban India. A common Open Ground Storey and a Stepped irregular framed building are revealed in Figure 1.1.



**Figure 1.1 Vertically irregular buildings**

Open ground storey structures may also be known as ‘open first storey buildings’ or perhaps ‘pilotis’ ‘stilted buildings’. Due to the scarcity of land, the earth storey is kept open for no infill and parking purpose walls are provided in ground storey although all above storey are as supplied with infill walls

The 2001 Bhuj earthquake (Magnitude M7.9 and PGA 0.11g) was among the most devastating a person to witness the collapse of several open ground storey RC buildings. A typical open ground storey residential building at Ahmadabad. The soil storey columns are badly harmed as found in Figure 1.2 (a) & (b). Figure 1.3 displays the failure of the very first storey columns as a result of shear in Earthquake.

## 1.2 CRITERIA FOR VERTICAL IRREGULARITY IN BUILDINGS

In the prior code of Is actually 1893, there was no design recommendations particularly for OGS frames mentioned for vertical irregularity. However in the aftermath of Bhuj earthquake was revised in 2002. In the latest version of code Is actually 1893 (2002) (part1)-, incorporated a brand new design recommendation for OGS buildings.

Clause 7.10.3 (a) states "The columns & beams of the soft storey are to be designed for 2.5 times the storey shear and moments calculated under seismic load of bare frame type of buildings". The magnification factor (MF) 2.5 is examined by Subramanian (2004), Kanitkar and Kanitkar (2001 Kaushik and (2006). The Magnification factor MF 2.5 is not advisable for design of beam as that very likely to end up a "strong beam- weak column" situation.

It needs not to develop the beams of the soft-storey additionally to design for larger storey shears as highly recommended by the above mentioned clause. Strengthening of beams will even further increase the need on the columns, and also deny the plastic development within the beams. These suggestions have met with a bit of opposition in style & construction practice due to congestion of heavy reinforcement within the column.

As per is actually 1893 (2002) code, 5 kinds of irregularities for structures are listed out as follows:

**i) a) Stiffness Irregularity - Soft Story:** is identified to occur when there's a story in which the lateral stiffness is under 70 % of which within the story above or perhaps less than 80 % of the common stiffness of the 3 stories above.

**b) Stiffness Irregularity - Extreme Soft Story** is identified to occur where there's a story in which the lateral stiffness is under 60 % of which within the story above or perhaps under 70 % of the common stiffness of the three stories above.

**ii) Weight (Mass) Irregularity** - It's deemed to occur where real mass of every story is much more than 150 % of the effective mass of an adjacent story.

**iii) Vertical geometric irregularity** - It shall be regarded as to occur where horizontal dimension of the lateral force resisting method in virtually any story is much more than 130 % of which within an adjacent story.

**iv) In plane Discontinuity** - In Vertical Lateral-Force-Resisting Elements is defined to exist where an in plane offset of the lateral-force-resisting elements is greater than the length of those components or even where there's a decrease in stiffness of the resisting component within the story below.

v) **Discontinuity in Capacity** - The weak story is only one in that the story lateral strength is under 80 % of which in the above mentioned story. The story lateral strength is definitely the complete lateral strength of all the seismic-resisting elements sharing the story shear in the consideration direction.

### 1.3 STEPPED BUILDINGS

Reduction of lateral dimension of the structure along their level is categorized as "stepped building". Due to the aesthetic and functional design these types of buildings are chosen in contemporary multi storey building construction.

### 1.4 BARE FRAME BUILDINGS

As per the Indian standard code for earthquake resistance structure created it's talked about that while developing a framework the contribution of infill are neglected. The

Buildings are specially designed as a bare frame which will be the sole style of columns and also beams are looked at. In the seismic point of view this's the worst case as compared to various other building sorts in which the vulnerability is more money against lateral lots due to the lack of the infill..

### 1.5 TYPICAL INFILLED MASONRY BUILDINGS

The usual infill masonry structures will be the regular buildings considering infill walls provided uniformly throughout the components which improve the power and stiffness of the components. The infill walls are viewed as a non-structural component from the convenience design practice as per Is actually code. But in the particular exercise the presence of infill walls create a strut compressive action acting diagonally in the path opposite to the use of the lateral pressure which might attempt to counter act the lateral force which causes less deflection. In a bare frame, the opposition to lateral force happens by the development of bending moments and also shears forces in the different columns and beams through the rigid jointed activity of the beam column joints, but in the situation of infill frame due to the strut action, causing reduced bending moments but improved axial forces within the beams & columns.

### 1.6 TYPICAL OPEN GROUND STOREY (OGS) BUILDING

Due to the lack of the infill walls in the ground storey which of existing at the storey above, the stiffness is abrupt decreases that are called as stiffness irregularity.

The base shear is registered through the ground storey columns. Due to the increased the shear pressure will cause the increased bending moment and thereby greater curvature which may possibly will higher inter storey drift formation at the ground storey which enhance by the  $P\Delta$  effect the plastic hinges are formed. Top of the shop will go as one block. This kind of collapse is called as smooth storey collapse. Due to the reduction in the stiffness at ground storey this particular kind of buildings are viewed as probably the most susceptible sort through the seismic point of view. The fig reveals the soft storey collapse of typical OGS structures.

### 1.7 PROBLEM STATEMENT

The majority of the residential buildings have been developed just for live and dead loads. Individuals are not conscious of the seismic design of buildings. But for the different buildings that are placed in the zone IV or V really needs being seismic resistant.

In this particular thesis, a current building has become undertaken for retrofitting. Think about a G+ 9 storey residential present building. It's a framed structure with complete eight stories above ground level. The ground level is an open storey being used as parking. It hence makes up a soft storey. On the roof, there's a water tank also. This particular building has been designed for the dead and the live a lot only. Consequently, two primary issues are determined in this particular building with respect to the seismicity of the structure. Firstly, the structure hasn't integrated in it the Earthquake loads. Second, no provisions are made up for the current soft storey. Thus, ground storey has to be provided with particular attention.

### 1.8 OBJECTIVE

The main objective of this particular study

1 To understand the behavior of the structure in higher seismic zone. In this purpose a 10 storey-high building on eight various configurations having re-entrant sides with a typical setup

2 To study IS Code 1893 (Part I): 2002 the entire models have been analysed with the help of STAADPro.

3 The present study additionally considered the accidental torsion in each positive and negative of both Y and X directions

### 1.9 SCOPE AND LIMITATION OF PROJECT

The RC framed Buildings are considered for the analysis by assuming regular in plan. The Out of plane action of walls is neglected in the analysis. The asymmetric arrangement of walls is ignored of the buildings. The Soil structure interaction effects are not considered in the analysis. The Flexibility of floor diaphragms are neglected and considered as rigid diaphragm. The base of the column is assumed to be fixed in the analysis.

## II. LITERATURE REVIEW

**Afarani and Nicknam et al. (2012) (1)** observed the behaviour of the vertically irregular building under seismic loads by Incremental Dynamic Analysis. They've talking about eight stories regular building using two bays with four m width in y direction has and four bays with three m width in x direction with three m storey height is believed. They considered Dead load as two ton/m is sent out on beams. In order to stay away from torsional effects they considered symmetric building and also steel moment resisting frames that are created based on IBC 2006 and ANSI/AISC 360-05

**FEMA 440 et al. (2000) (2)** studied Eighteen ground motion records from Pacific Earthquake Engineering Research Centre (PEER) database are collected from Far Field with distance far more than ten km from site as well as have Richter magnitudes of five to eight on firm soil. The structure is modelled in SeismoStruct-V5 software as a nonlinear dynamic analysis, Steel is modelled as Elastic Perfectly Plastic (EPP) hysteresis with no expertise of lateral and local buckling and the connections happened to be failure according to FEMA 440. Maximum inter story drift ratios and first mode spectral acceleration are calculated by Incremental dynamic analysis and IDA curved are plotted to get the collapse points. The evaluation of the structure is targeted on the collapse prevention limit state of the components. Fragility curves are generated by using Cumulative Distribution Function via the lognormal distribution through collapse points

**Elnashai and Jeong et al. (2006) (3)** research the fragility analysis for an irregular RC building under bidirectional earthquake loading has studied by For the account of the irregularities in structure, bidirectional response and the torsion are used as 3d structural response features to represent the destruction states of the structure irregularities is provided through a reference derivation. A 3 story RC frame is obtained with asymmetric in plan with thickness of slab is 150 mm and beam depth is 500 mm to learn the damage assessments. The sectional dimension of C6 is 750×250 mm whereas almost all some other columns are 250×250 mm. Fragility curves are produced by calculating the destruction measure with spatial (3D) damage index by statistical manipulation techniques & lognormal distributions for response variables Earthquake records consist are of two orthogonal components Transverse and (Longitudinal) of horizontal accelerations and are customized from the organic documents being suitable for a smooth code spectrum. PGAs are taken away from arange of 0.05 to 0.4g with a step of 0.05g. For correct damage assessment of buildings is exhibiting torsion, Planar decomposition technique is used where construction is decomposed into planar frame and analysed. The parameters such as for instance best displacement, inter-story drift or even a harm index are found out from numerical simulations results. The total damage index is estimated for the planar frames in the backbone envelope curve as a mix of harm due to in plane monotonic displacement plus strength reduction. Coefficient of variation (COV) is discovered function as the ratio of standard deviation to mean value of damage index

**Tantala and Deodatis et al. (2002) (4)** analysis a 25 story of reinforced concrete moment resisting frame Building having three-bays. generated fragility curves a they've a they've broad variety of ground motion intensities. They've utilized a bit of time histories are modelled by stochastic processes. Simulation is accomplished by power spectrum probability and duration of earthquake by conducting 1000 simulation for every parameter. The nonlinear analysis is done by considering the P-Δ effects and by ignoring soil-structure interaction. They have considered the nonlinearity in material properties in model with nonlinear rotational springs a bilinear moment-curvature relationship by since the stiffness degradation through hysteretic energy dissipation capacity over successive cycles of the hysteresis. They've utilized Monte Carlo simulation approach for simulation of the ground motion. The simulation with the durations of effective ground motions is completed at two, seven and twelve second's labels to look at the consequences. They thought the consequences on the assumption of Duration and gaussianity. They've implemented stochastic process for modelling. The analyses have been carried out by utilizing DRAIN-2D like a dynamic analysis with inelastic time records data. The arbitrary material strengths have been simulated for virtually any column and beam using Latin Hypercube sampling.

**Murat and Zekeria et al. (2006) (5)** studied the yielding and also collapse behaviour of RC frame buildings in Istanbul was analysed through fragility analysis primarily based on numerical simulation. They've studied amount of accounts of

buildings as three, five & seven storeys designed as per Turkish seismic design code (1975). The fragility curves have been designed with the assistance of the outcomes of regression analysis. They've examined with twelve artificial ground motions because of the evaluation. Incremental powerful analysis (IDA) method is employed for estimating structural performance under many ground motions. The Characteristic strength of concrete as 16Mpa and 2 completely different steel type as 220Mpa & 420Mpa are used. The anxiety because of scatter of substance along with the soil structure interaction was dismissed in their layout mean importance of material power was taken into account that had been examined experimentally. Performance limit state in elastic displacement demand as well as corresponding deformations for fast collapse and occupancy prevention is evaluated. From the fragility curves last they've realized that with the collapse prevention performance level, a good correlation between spectral displacement limit and also the quantity of stories was noticed though similar observation wasn't valid for the instant occupancy level.

**Rota et al (2010) (6)** observed the fragility curves for masonry buildings prototype of a three-storey masonry building located in Benevento (southern Italy) that has built in 1952 are analysed primarily based on stochastic nonlinear analysis. The variables can be found out by Monte Carlo simulation by way of an application STAC for the evaluation. The structure used is basically tuff masonry many experimental tests have performed by Faella et al. The program TREMURI, a frame type macro element worldwide analysis program was developed by Lagomarsino and Gambarotta as well as further modified by Penna for any nonlinear pushover plus time history analyses on masonry Buildings. In this particular research various sources of uncertainty are associated with the issue, by derivation of the probability distributions of equally demand and capacity through 3d nonlinear analyses of entire structure. They have used in plane cyclic shear compression tests completed on specimens made of cement mortar and also tuff units. The evaluation has been carried out by considering four mechanical damages for the components. 2 of them may be recognized from the result of one masonry pier even though the other 2 can be found from the worldwide response of the structure. For starters damage state is determined through the attainment of the yield displacement is  $y$  of the bilinear approximation to the capability curve associated with one masonry pier. The next damage state is determined by the drift corresponding to the very first shear cracking of the pier is  $S$  which gotten through the experimental test. The fourth and third damage states in America have been derived from worldwide pushover curves of the structure since the 3rd status is assumed to match to the attainment of the optimum shear resistance while the fourth phase corresponds to the attainment of eighty % of that significance. All the physical qualities of the structure are assumed to be random variables; standard deviations and the mean value are calculated by normal probability distributions of the construction typology

**Erberik et al. (2008) (7)** studied the mid-rise and low-rise reinforced concrete (RC) buildings through Fragility analysis which qualities within the Duzce Damage database that affected by 2 devastating earthquakes in 1999 at Marmara region in turkey. They have considered the structures of amount of stories ranges between 2 and 6. In the analysis the structure having 2 and 3 stories are viewed as low rise (Buildings and  $I_r$ ) having 4 to 6 stories are viewed as mid-rise (MR). They have studied with twenty eight RC buildings obtained from a construction collection of around 500 buildings in Duzce. Post-earthquake damage assessments of the buildings had been readily available. The Duzce damage data source is widely used earlier by some other researchers. 100 corrected ground motion records have collected from various regions of the planet with a selection of magnitude between 5.1 and 7.8 are employed for the evaluation. The ground motion set is split into twenty Groups all of 5 with PGV time periods of five cm/s, the structures are modelled as bare frame or maybe infill frame. In the research they subdivided the structure as low rise bare frame type, low rise infill frame type, mid-rise bare frame style and also mid-rise infill frame type.

The mid-rise and low-rise RC structures are analysed as one level of independence process with the worldwide response statistics of simplified (or maybe equivalent) analytical models.

**Guneyisi and Altay et al. (2008) (8)** observed the behaviour of current R/C office buildings through fragility curves thinking about the circumstances as before and also after retrofitted by fluid viscous (VS) dampers. Braced frames are viewed at the middle bay of the frame with passive fluid VS dampers at every brace. A 12 storey office building designed as Turkish seismic design code version (1975) from Istanbul. VS dampers are utilized for retrofitting specially designed as FEMA 273-274 with many different effective damping ratios of ten %, , and 15 % and 20%. Main structural method of the structure includes moment resisting R/C frames in 2 directions with 12-storey located at average seismic zone with fairly rigid soil type as per Turkish seismic design code has taken. The storey position of the structure is 2.75 m with 989 m<sup>2</sup> floor area. 240 earthquake ground motions are generated by considering the spectral representation strategy according to the stochastic engineering Approach by using MATLAB program limited to 1PGA. The R/C building is modelled as a three dimensional analytical type of the structure was started in ETABS version 7.2 Structural Analysis Program for the evaluation. For the seismic result of the buildings are concentrated

through the nonlinear time history analyses with push over analysis by IDARC version 6.1 programs. The distinctive energy and yield

strength is viewed as of 16 MPa and 220 MPa. The fragility curves are generated for

4 damage states as slight, major, moderate, as well collapse conditions plus Load deformation connection just for the vulnerable axis (y axis) and also the structural damage limit values found for every damage type. The fragility curve produced for the structure are realized that with the assistance of retrofitting the failure risks of creating is minimized so that the before retrofitting is much more flimsy than after retrofitting case.

**Samoah et al. (2012) (9)** observed the fragility behaviour of non-ductile reinforced concrete (RC) frame buildings in lower - medium seismic areas and they've chosen at Accra that's the capital of Ghana, West Africa. The structural capability of the buildings is analysed by inelastic pushover analysis and seismic demand is analysed by inelastic time history analyses. Then the fragility curves are drawn. They've analyzed with three generic no ductile RC frame buildings using regular and symmetrical in each program and elevation are made based on BS 8110 (1985). The buildings taken into account are a 3- 3-bay and storey, a 2-bay and 4-storey and a 6 storey and three bay structures to get a suitable consequence. The structure was modelled using thirty five as well as sixty % of the yucky sectional areas of columns and beams. A macro element program IDARC2D (1996) was produced as the inelastic static and dynamic analysis of non-ductile RC frames. Theevaluation for the non-ductile RC frame buildings, modelling are successfully done properly depending on the structural properties of theirs.

**Rajeev and Tesfamariam et al.(2012) (10)** analyzed the seismic overall performance of non-code conforming RC structures created for gravity loads. The analysis highlights the necessity for reliable vulnerability assessment and retrofitting. The vulnerability is compounded since the RC buildings are subject to various problems such as for instance weak storey, soft storey, plan irregularities sand various other types Fragility based seismic vulnerability of structures with consideration of very soft storey(SS) plus quality of construction(CQ) is evidenced on three, five, and also nine storey RC frames created prior to 1970s. Probabilistic seismic demand model (PSDM) for considered structures is produced, by utilizing the nonlinear finite element analysis. Additionally, the fragility curves are created for the 3 structuresconsidering of, CQ, and SS the interactions of theirs. Finally, confidence bounds within the fragilities are also provided as a measure of the accuracy of theirs for risk informed decision-making. With the PSDM models the corresponding fragility curves are generated. in the evaluation. They realized that the vertical construction and irregularities quality in seismic risk assessment enjoy a major influence within the decision making stage. The proposed strategy of creating a predictive tool is able to improve local damage assessment tool, for example HAZUS, to build enhanced fragility curves for known CQ and SS.

**Menon and Davis et al. (2004)(11)** examined the presence of masonry infill panels modifies the structural force distribution considerably within an OGS building. They considered verities of creating case studies by boosting the storey heights plus bays in OGS buildings to study the modification in the behaviour of the functionality of the structures with the increased the variety of bays and storey also the storey heights. They found that with the total storey shear force improves since the stiffness of the structure improves within the presence of masonry infill at top of the flooring of the structure. Furthermore, the bending moments in the ground the failure and floor columns increase is created because of delicate storey mechanism which would be the development of hinges in ground storey columns.

**Scarlet et al. (1997) (12)**identified the qualification of seismic forces of OGS buildings. A multiplication factor for base shear for OGS building was offered. The modelling thestiffness of the infill walls in the evaluation was focused. The result of in Multiplication element with the increased storey height was studied. He observed the multiplication factor ranging from 1.86 to 3.28 as the amount of storey increases from 6 to 20.

**Hashmi and Madan et al. (2008) (13)** conducted nonlinear time historical past plus pushover analysis of OGS buildings. They realized that the MF recommended by Is actually 1893 2002 for such buildings is enough for stopping collapse.

**Sahoo et al. (2008) (14)**observed the behaviour of open-ground-storey of Reinforced concrete (RC) framed buildings having masonry at above storey by employing Steel Caging along with Aluminum Shear Yielding Dampers. He's created an easy spring mass item for the layout of braces for enough power and stiffness needs of the strengthening program. A shot a five storey four bay non ductile RC frame having open ground storey for his observation. And furthermore decreased scale 1storey one bay RC frame was analysed experimentally under continual gravity loads and reversed cyclic slowly increasing lateral Displacement by Full strengthening technique. For flexural strength and also inelastic rotation at a goal yield mechanism the performance based design technique was created to withstand the likely

seismic demand as the lateral strength, inelastic deformation and also electric energy dissipation demand on structures. He noticed for load transferring assemblies the steel cage-to-RC footing brace-to-steel cage connection and connection exhibited performance that is excellent under lateral cyclic loading with no signal of early failures. Whereas the RC frame strengthened with just steel caging exhibited the improved lateral strength, drift capacity and power dissipation potential when compared to the non-ductile frame but couldn't stay away from collapse completely

**Patel et al. (2012) (15)** proposed both linear as the Equivalent Static Response and Analysis Spectrum Analysis as well as the nonlinear analyses as the Pushover Analysis and also Time History Analysis for Low rise open ground storey framed building with infill wall stiffness as being an equivalent diagonal strut model. The result on the infill wall is studied considering the Indian standard code Is actually 1893 2002 criteria mention for OGS buildings. She found that the evaluation results demonstrate a MF of 2.5 is pretty high to always be multiplied towards the beam and column forces of the soil storey of the structures. Their study determine that the issue of open ground storey buildings can't be identified properly through elastic analysis since the stiffness of open ground storey creating along with a comparable bare frame construction are just about identical.

**Sarkar et al (2009)(16)** research the irregularity in stepped framed building by considering Regularity index. 78 building frames with even number plus bay width of four and 6m respectively with varying level of stepped irregularity are deemed 7 amounts of structures with various level can also be provided without considering step. 50 modes are focused for 4 distinct situations of building. They noticed by histogram that with the increases in irregularity, the first mode participation decreases with higher participation on some higher modes. Delhi Secretariat building ten storied office building placed in New Delhi (Seismic Zone IV with designed PGA of 0.24g as per Is actually 1893:2002). The modelling and evaluation had been carried out by utilizing an application SAP2000.

**Kim & Shinozuka et al. (2004) (17)** studied the fragility assessment of 2 sample bridges retrofitted by steel jacketing of bridge columns in southern California. Among the 2 bridges the first one bridge was 34m very long with 3 span with 2 half shells of rolled steel plate and a RC deck slab 10m width supported by 2 pairs of circular columns (each having three columns of diameter as 0.8 m) with abutments. And also the 2nd bridge was 242m long with a deck slab dimension (13m wide & 2m deep) that supported by four circular columns of 2.4m diameter and level of 21m have an expansion joint at centre was taken. 60 ground acceleration time records have been collected from the Los Angeles the historic documents then Adjusted. After which and then they've grouped into 3 groups each of owning 20 data. The bridges had been modelled as a two dimensional response analysis with a computer system program SAP2000 and also nonlinear limited method. The fragility curves were developed by considering before and also after column retrofit with steel jackets cases with probabilities of exceedence of ten % in fifty years, two % in fifty years as well as fifty % in 50 years, respectively. Nonlinear response characteristics connected with the bridges are based on moment-curvature curve analysis. They considered two parameter lognormal distributions operates by the median and log standard deviation to analysis the fragility curves. They have completed the evaluation for performance levels that are different as no cracking, Slight Cracking Moderate, Extensive Incipient column collapse Complete. The fragility curves were Produced from the experimental outputs then compared.

**Zentner et al (2008) (18)** observed the seismic probabilistic risk assessment (PRA) for seismic risk assessment of nuclear plant life is examined through fragility evaluation within the evaluation. They considered coupled model consisting associated with a supporting framework which is containment building modelled as 3d stick model and likewise the secondary method which represent a reactor coolant process that is certainly modelled as a beam elements comprises of a reactor vessel and four loops experiencing steam generator. Primary pump plus piping in every loop is multisupported by 36 supports. 4 top lateral supports placed at the upper part of every steam generator along with 3 smaller lateral supports for safety and guidance of steam generator & reactor vessel. Statical estimation of parameters through fragility curves for any nuclear power plant was examined using numerical simulation.. They've generated fifty artificial ground motions time records and analysed as a nonlinear dynamic effect of the website response spectrum for a rocky site. The soil motions are modelled by stochastic process from man-made time records data. Each of the numerical computations they have performed implementing Code Aster open source FE software for the paper results. They have considered 2 configurations in the evaluation. Very first they've considered the concerns regarding earthquake and soil in the evaluation after which they thought the concerns as a result of earthquake ground motion in addition to structural and method within the plant equipment.

**Guneyisi and ozel et al. (2011) (19)** studied a mid-rise RC frame building retrofitted with eccentric steel brace was observed through Fragility analysis. A 6 storey RC frame building, designed as per Turkish seismic design code 1975 placed in a high seismicity area of Turkey was consumed the research. In making normal beam and also column was

considered with no shear wall. The steel braces (K,V&D type) they've worn 4 different distribution to view the behaviour. The fragility curves have been created from the inter storey drift by way of nonlinear time history analysis. The fragility curves created for the first putting together for several damage levels. 200 earthquake information have been considered that produced by utilizing MATLAB program. Modelling was conducted as a 2D analysis by using a software SAP2000 nonlinear version 11. The median and standard deviation of the ground motion indices for every injury fitness level had been acquired by performing linear regression analysis for various performance levels. They observed the various damage levels as slight, major, moderate, as well as collapse for the construction. The fragility curves were designed for before and also after retrofitting with metal braces. They realized after retrofitting with steel braces had been much less fragile than all those before retrofit. Plus the distributions of the eccentric steel braces had been somewhat impacting the seismic reliability of the braced frames. First distributions (K1, V1, or maybe D1) provided the fourth and greatest distributions (K4, V4, or maybe D4) provided the very least seismic reliability.

**Marano et al (2011) (20)** finds the fragility curves are created that according to the category and also components supplied by the Hazus database with the applications of stochastic compelling analysis. Kinds for all the structures are considered as two storeys & five storeys buildings with equally low seismic style and medium seismic design are thought about. A displacement based damage index is used for the fragility analysis. The anatomical structure considered is a nonlinear single amount of independence system (SDOF). Response to seismic activity, modelled by means of the modulated Penzien and Clough procedure, is attained through the use of stochastic linearization technique & covariance analysis. Fragility curves are gotten using an approximate threshold crossings theory. A sensitivity analysis continues to be done with respect to structural details as well as discussing various soil types. From the sensitivity analysis performed considering structural mechanical details it could be deduced that all of the variables adversely affect the fragility curves, except the stiffness ratio  $\alpha$  which influences just the fragility curve that corresponds to the weighty damage state

**Pallav et al (2012) (21)** estimated the spectral acceleration on the Manipur region through the probabilistic seismic hazard analysis (PSHA). The region considered for the evaluation is divided into various zones. By factor of past earthquake data the earthquake recurrence relations are examined for the evaluation. Seenapati, tamenglong, churachandpur, chandel, Ukhrul, Imphal west, imphal east, Bishnupur and Thoubal places belongs to that particular region are viewed for the evaluation. Counter maps are considered for the different places of Manipur region by thinking about the variation of good ground acceleration for return periods. These benefits might be of use to engineers and planners for choice of site, earthquake resistant structures designing and, might assist the state administration in seismic hazard mitigation

**Ellingwood et al. (2001) (22)** calculated the earthquake danger assessment of the structure by using the probabilistic risk analysis resources for 2 years. He concentrated on the 3 probability based codified designed and reliability based condition assessment of existing buildings. The steel frames weld connected are designed. A nonlinear compelling examination is done studying the behaviour in the benefits of inherent randomness and also modelling uncertainties within the functionality of the structures through fragility analysis. The seismic hazard analysis is done by thinking about the ground motion from California powerful ground motion network.

**Celik and Ellingwood et al. (2010)(23)** observe the seismic functionality of the reinforced concrete frames is in the hands of low seismic area are intended and also analysed for gravity loads. They considered the uncertainty in the content qualities & structural methods (i.e. structural damping, concrete strength, and also cracking strain in beam-column joints have the greatest effect on the fragilities of such frames. Confidence bounds within the fragilities are also provided as a degree of the accuracy of theirs for risk informed decision-making, for prioritizing risk mitigation work in areas of low-to-moderate seismicity.

**Bhattacharya et al (2001) (24)** focused on the development of the target reliability of the novel structures that calibrated to existing structures. They adopted a general risk methodology of reliability framework is considered for finding out the significant limit state and the identification of the target reliability for the structures analytically. The methodology is illustrated with the US Navy's Mobile Offshore Base concept is the unique offshore structure in terms of function and size, and where no industry standard exists. A survey of reliability levels in existing design standards and engineered structures, target reliabilities recommended by experts, and analytical models for establishing acceptable failure probabilities is presented. The MOB target reliabilities presented here are subject to modification in the actual acquisition phase when more input becomes available. It is concluded that setting target reliabilities for high-value novel structures is not an engineering decision alone active involvement on the part of the owners and policy-



makers is also required.

**Sykora, M., & Holicky, M., et al. (2011) (25)** investigated the same target reliability level for the assessment of existing structures. The variation of the cost as well as the reliability index is determined by considering the different parameters. By considering the various codes the target reliability has estimated for the building and based upon this the performance levels are evaluated. The target reliability levels are primarily dependent on the failure consequences and on the marginal cost per unit of a decision parameter; upgrade costs independent of the decision parameter; remaining working life and discount ratio are less significant. The design values are specified on the basis of an appropriate reliability index ( $\beta$ ).

### Summary

Overviews of guidelines for vertically irregular buildings are carried out in the first chapter. The review of the study indicates that there are numerous research efforts found on the seismic behaviour of RC buildings, OGS buildings also with regard to seismic performance of the vertically irregular buildings, there are few studies conducted. But all this studies are based on a deterministic approach. The main motivation is to study the performance of the vertically irregular buildings and to fine tune the design guidelines as per the Indian standards. For example, with regard to an OGS building, the IS 1893(2002) suggests a multiplication factor of 2.5 for ground storey columns. The multiplication factor proposed by IS 1893 (2002) needs to be more of rational than an empirical number. The seismic hazard analysis is adopted for the OGS buildings and the stepped type buildings by considering the criteria from various codes by identifying the reliability index calculation for the buildings to evaluate the appropriate MF values for the design of the buildings belongs to various region of India.

### III.CONCLUSION

Considering the storey displacement, the frame and structure with floating columns (frame 2) may be the most fragile since it suffers the highest displacement as the base frame and structure exhibits the very least displacement. So far as storey drift is concerned, frame two (with bottom 2 soft storeys) may be the most fragile since it's the maximum storey drift which changes abruptly. Frame 8 also shows pattern that is similar for bottom 2 storeys. Storey shear is however maximum in frame four and structure four (with 3rd and 6th storeys major). It may be inferred naturally the frame and structure with floating columns represents the even worse situation since it faces the highest displacement and is very susceptible to damages under this particular lateral loading. While, on the flip side it could be observed that the base frame and structure contains the very least drift and displacement, hence least vulnerable to the harm. In this particular thesis different structures and frames having completely different irregularities but with exactly the same dimension were analysed to learn their behaviour when put through lateral loads. All of the frames and also components have been analysed with exactly the same technique as mentioned in IS actually 1893 part 1: 2002. The starting frame and structure that is ideal develops least story drifts while the structure with floating column shows maximum storey drifts on soft story levels. Thus this's probably the most susceptible to damages under this particular type of loading. The many other structures with irregularities also proved unsatisfactory success to some degree. The frame with heavy loads produces maximum storey shears that should always be accounted for in design of columns suitably. The analysis reveals the dynamic approach provides us much more refined results as than static evaluation of the structure.

The evaluation too demonstrates that irregularities are unsafe for the buildings and also it's crucial that you have regular and simpler shapes of frames in addition to even load distribution within the construction. Thus, as much as potential irregularities in a construction should be avoided. But if irregularities need to be introduced without any reason, they should be designed effectively adhering to the circumstances of IS actually 13920: 1993. And now days, complex shaped buildings are becoming famous though they have a threat of sustaining damages during earthquakes. Therefore such structures must be created effectively taking care their dynamic behaviour

### REFERENCES

- 1 Afarani, M., and Nicknam, A. (2012). "Assessment of Collapse Safety of Stiffness Irregular SMRF Structures According to IDA Approach." J. Basic and Applied Scientific Research, 2 (7), 6566-6573.
- 2 FEMA 356 (2000). "Pre-standard and Commentary for the Seismic Rehabilitation of Buildings." J. ASCE, USA.
- 3 Jeong, S.H., and Elnashai, A.S., (2006). "fragility analysis of buildings with plan irregularities." 4th International Conference on Earthquake Engineering, Paper No. 145. October 12-13.
- 4 Tantala, M. W., and Deodatis, G (2002). "Development of seismic fragility curves for tall buildings." 15th ASCE engg mechanics conference, June 2-5, Columbia university, New York.

- 5Murat, S. K., and Zekeria, P. (2006) "Fragility analysis of mid-rise R/C frame buildings." J. Earthquake Engineering and Structural Dynamics, 28 1603–26.
- 6 Rota, M., Penna, A., and Magenes, G. (2010). "A methodology for deriving analytical fragility curves for masonry buildings based on stochastic nonlinear analyses." J. Engineering Structures 32 1312\_1323.
- 7 Erberik, A.M. (2008). "Fragility-based assessment of typical mid-rise and low-rise RC buildings in Turkey." J. Engineering Structures, 30 1360–1374.
- 8 Guneyisi, E.M., and Altay, G. (2008). "Seismic fragility assessment of effectiveness of viscous dampers in R/C buildings under scenario earthquakes." J. Structural Safety, 30 461–480.
- 9 Samoah, M. (2012). "Generation of analytical fragility curves for Ghanaian non-ductile reinforced concrete frame buildings." J. Physical Sciences Vol. 7(19), pp. 2735-2744.
- 10 Rajeev, P., and Tesfamariam, S. (2012). "Seismic fragilities for reinforced concrete buildings with consideration of irregularities." J. Structural Safety, 39 1–13.
- 11 Sarkar, P., Meher, A., Prasad., Menon, D. (2010). "Vertical geometric irregularity in stepped building frames." J. Engineering Structures, 2175\_2182.
- 12 Scarlet, A. (1997). "Design of Soft Stories – A simplified energy approach.", J. Earthquake Spectra. 13. 305-315.
- 13 Hashmi, A. K., and Madan. A. (2008). "Damage forecast for masonry infilled reinforced concrete framed buildings subjected to earthquakes in India." J. Current Science. 94. 61-73.
- 14 Sahoo, D. R. (2012). "Seismic Strengthening of Reinforced Concrete Framed Structures-Using Steel Caging and Aluminium Shear Yielding Dampers", Lambert Academic Publishing GmbH & Co. KG, Germany
- 15 Patel, S. (2012). "Earthquake Resistant Design Of Low-Rise Open Ground Storey Framed Building." M. Tech Thesis, National Institute of Technology, Rourkela.
- 16 Sarkar, P., Meher, A., Prasad., Menon, D. (2010). "Vertical geometric irregularity in stepped building frames." J. Engineering Structures, 2175\_2182.
- 17 Im, S.H., & Shinozuka, M. (2004). "Development of fragility curves of bridges retrofitted by column jacketing." J. Probabilistic Engineering Mechanics, 19 105–112.
- 18 Zentner, I., Borgonovo, E., Pellegrini, A., and Tarantola, S. (2008). "Numerical calculation of fragility curves for probabilistic seismic risk assessment" The 14th World Conference on Earthquake Engineering, Oct 12-17, China
- 19 Guneyisi, E.M., and Altay, G. (2008). "Seismic fragility assessment of effectiveness of viscous dampers in R/C buildings under scenario earthquakes." J. Structural Safety, 30 461–480.
- 20 Marano G.C. et al (2011). "Analytical evaluation of essential facilities fragility curves by using a stochastic approach." J. Engineering Structures, 33 191–201
- 21 Pallav, K., Raghukanth, S. T. G., and Singh, K. D., (2011) " Probabilistic seismic hazard estimation of Manipur, India." J. Geophysics And Engineering, doi:10.1088/1742-2132/9/5/516.
- 22 Ellingwood, B. R. (2001). "Earthquake risk assessment of building structures." J. Reliability engineering and system safety, vol. 74, pp. 251-262.
- 23 Ellingwood, B. R. (2001). "Earthquake risk assessment of building structures." J. Reliability engineering and system safety, vol. 74, pp. 251-262.
- 24 Bhattacharya, B., Basu, R., and Ma, K.T. (2001). "Developing target reliability for novel structures: the case of the Mobile Offshore Base." J. Marine Structures, 14 37 58.
- 25 Sykora, M., Holicky, M. And Markova, J. (2011). "Target reliability levels for assessment of existing structures.", M.H. Faber, J. Köhler And K. Nishijima, eds. In: Proc. ICASP11, 1-4 August 2011 2011, CRC Press/Balkema, pp. 1048-1056.